

Config. program V1.01
Firmware for BDI2000 V1.01
Logic for BDI2000 V1.06



Date: January 6, 2006
Page: 1/1

Enhancements

- Telnet history buffer no longer filled with repeated commands.
- The Windows setup tools now allows to select a COM port in the range 1 - 19.
- The Telnet CONFIG command displays the firmware version.

Error Correction

- Correct single step of the Thumb BX pc instruction.
- Correct handling of ARM/Thumb mode switch while in debug state.

Config. program V1.01
Firmware for BDI2000 V1.02
Logic for BDI2000 V1.06



Date: June 9, 2006
Page: 1/1

Enhancements

- Enhanced flash erase support via configuration file (see user's manual).
- Improved Telnet history buffer handling.
- Support for low level scan chain configuration added (see user's manual).

Error Correction

- Correct display of banked registers (rdall command).

Config. program V1.01
Firmware for BDI2000 V1.03
Logic for BDI2000 V1.06



Date: June 22, 2007
Page: 1/1

Enhancements

- New flash algorithm types added (S29M64X8, S29M32X16).
- The MirrorBit algorithm uses the write buffer also when no workspace is defined.
- New RECONNECT option to the DEBUGPORT parameter added. When present, a Telnet/GDB (TCP) connection request to an already open TCP channel is accepted if the host IP is the same as the initial one. The old TCP channel will be closed immediately.
- Telnet accepts now multiple commands separated by a semi-colon on one line.

Config. program V1.02
Firmware for BDI2000 V1.04
Logic for BDI2000 V1.06



Date: Oct 28, 2007

Page: 1/1

Enhancements

- Support for Cortex-A8 (OMAP3430) added.

Config. program V1.02
Firmware for BDI2000 V1.05
Logic for BDI2000 V1.06



Date: January 3, 2008
Page: 1/1

Enhancements

- The new CLOCK init list entry allows to change the JTAG clock frequency during processing of the init list. Maybe useful to switch to a faster clock as soon as possible.
- Improved memory access for Cortex-A8
- Improved OMAP3430 reset sequence.

Error Correction

- Error in I28BX16 target programming algorithm corrected. Programming with workspace was very slow because the algorithm did not enter debug mode after terminating.
- ARM11: The displayed cache TAG values are now correct.
- Cortex-A8: The RESET signal is now released at the end of the standard reset sequence.

Config. program V1.02
Firmware for BDI2000 V1.06
Logic for BDI2000 V1.06



Date: April 10, 2008

Page: 1/1

Error Correction

- Cortex-A8: Correct fast/stalled memory access sequences.

Config. program V1.02
Firmware for BDI2000 V1.07
Logic for BDI2000 V1.06



Date: July 9, 2008
Page: 1/1

Enhancements

- Support for ARM1176 and Cortex-M3 (STM32) added.
- Support for STM32F10xx internal flash programming added.

Config. program V1.02
Firmware for BDI2000 V1.08
Logic for BDI2000 V1.06 / 1.00



Date: Aug. 29, 2008
Page: 1/1

Enhancements

- Support for Luminary Micro Stellaris LM3S internal flash programming added.
- Support for Cortex-M3 / Cortex-A8 Single Wire Debug Mode added (different firmware).

Config. program V1.02
Firmware for BDI2000 V1.09
Logic for BDI2000 V1.06 / 1.00



Date: Febr. 25, 2009
Page: 1/1

Enhancements

- Support for Cortex-R4 added
- Support for ARM7 connected via JTAG-AP added (see manual).
- New parameter to select the single step mode added (see manual).
- New Telnet commands INTENA and INTDIS added.

Error Correction

- Correct single step of newer ARMv6/v7 instructions.

Config. program V1.02
Firmware for BDI2000 V1.10
Logic for BDI2000 V1.06 / 1.00



Date: Sept. 29, 2009

Page: 1/1

Enhancements

- Support for DAP-Lite module added.
- Support for multiple A8/A9 debug components behind one DAP added.
- Support for searching nested ROM tables added.
- APB base address of the debug component can be preset (no ROM table search).
- Download speed via GDB improved.
- Support for a different reset type for the initial power-up reset added (see manual).

Config. program V1.02
Firmware for BDI2000 V1.11
Logic for BDI2000 V1.06 / 1.01



Date: May 17, 2010

Page: 1/1

Enhancements

- Support for Atmel SAM3U / SAM3S internal flash programming added.
- SWD: Single Wire Output can be routed to a TCP/IP channel (see manual).

Config. program V1.02
Firmware for BDI2000 V1.12
Logic for BDI2000 V1.06 / 1.01



Date: August 20, 2010

Page: 1/1

Enhancements

- Support for Cortex-M0 added.
- Support for LPC1xxx flash programming added.