

Config. program ■ V1.01
Firmware for BDI3000 ■ V1.09

Date: June 20, 2008

Enhancements

- Enhanced Telnet „go“ and „halt“ command for MPC8572 dual-core processor.

Error Correction

- Error in e500 GDB register packet format corrected.

Config. program ■ V1.02
Firmware for BDI3000 ■ V1.10

Date: Febr. 13, 2009

Enhancements

- Support for MPC8536 added
- New MT Telnet command for a simple bus/memory test added.

Error Correction

- Error when single-stepping in JTAG mode corrected.

Config. program V1.02
Firmware for BDI3000 V1.11

Date: June 24, 2009

Enhancements

- Support for MPC8569 added
- Support for P2020 added

Config. program V1.02
Firmware for BDI3000 V1.12

Date: Febr. 12, 2010

Enhancements

- Support for Boot Page translation added, define „MMU XLAT 0xffff000“.
- Support for P2020 Rev.2 (new PVR) added.
- Download speed via GDB improved.
- Maximal number of software breakpoints increased to 64.
- Support for GDB p - packet (single register read) added.

Error Correction

- Display all 512 TLB0 entries for e500v2.

Config. program V1.02
Firmware for BDI3000 V1.13

Date: June 25, 2010

Enhancements

- Support for P1020 added
- Some GDB protocol improvements.

Config. program ■ V1.03
Firmware for BDI3000 ■ V1.14

Date: June 10, 2011

Enhancements

- Special reset sequence required for P1010/14 added.
- For some devices, overriding the Boot ROM Location is supported via the ROMLOC option.
- GDB hardware watch reporting enhanced by using the T05watch response packet.

Config. program V1.03
Firmware for BDI3000 V1.15

Date: Sept. 9, 2011

Enhancements

- Accept new e500v2 PVR numbers.