

Config. program      ■ V1.01  
Firmware for BDI3000   ■ V1.14

Date: May 2, 2008

## Enhancements

- Support for MPC8610 added.
- Hex display of FP register content via Telnet added.

## Error Correction

- 7448: Correct access to HID1 and ICTRL

Config. program      ■ V1.02  
Firmware for BDI3000   ■ V1.15

Date: April 22, 2009

## Error Correction

- 64-bit flash programming with workspace did not work at all. This has been fixed now.