

Config. program      ■ V1.02  
Firmware for BDI3000   ■ V1.19

Date: March 18, 2009

## Enhancements

- Improved Telnet MT command.
- New init list entry added that allows to set PC, HI and LO.

## Error Correction

- TLB handling crashed for cores with 64 TLB entries. This has been fixed now.

Config. program      ■ V1.03  
Firmware for BDI3000   ■ V1.20

Date: April 13, 2011

## Enhancements

- Support for MIPS 74K added.
- Download speed via GDB improved.
- Support for single step mode HWBP and SWBP for MIPS16 code added.

Config. program  V1.03  
Firmware for BDI3000  V1.21

Date: November 7, 2011

## Enhancements

- Support for Spansion S29GL-S flash added (S29GLSX16 algorithm)

## Error Correction

- Error when reading bytes from odd addresses corrected. This error was only present in version 1.20.