

Config. program ■ V1.02
Firmware for BDI3000 ■ V1.19

Date: March 18, 2009

Enhancements

- Improved Telnet MT command.
- New init list entry added that allows to set PC, HI and LO.

Error Correction

- TLB handling crashed for cores with 64 TLB entries. This has been fixed now.