

Config. program ■ V1.02
Firmware for BDI3000 ■ V1.12

Date: October 1, 2009

Enhancements

- Telnet accepts now multiple commands separated by a semi-colon on one line.
- Download speed via GDB improved.
- Telnet IAC option handling improved.

Error Correction

- Correct single step of newer ARMv6/v7 instructions.